

- 1937
- #5 Blast Furnace relined.
- 1938
- Bob Wier quit.
  - Ed Hackett quit.
  - New furnace built for 10" Skelp Mill, Bessemer.
- 1939
- #3 Blast Furnace completely rebuilt, including foundation.
- 1942
- Bruce Powrie fired.
  - Walter Cook became Field Engineer.
  - #1 Blast Furnace finished and put in service.
- 1945
- May -Kohlmorgen fired.
- 1946
- Mar. -Dave Lindsay started.
  - June -#2 Blast Furnace relined from mantle to the top.
  - #3 Blast Furnace fitted with high pressure top.
  - July -Pat Mele laid off.
  - Sept. -Flue dust sump at #3 Blast Furnace put in operation.
  - Oct. -New furnace complete with foundation in operation at 10" Skelp Mill, Bessemer.
  - Nov. -Geffel quit to return to the Army.
  - Went through #1, 2 and 4 Blast Furnaces on scaffolds.
  - Dec. -#2 Blast Furnace lined from the mantle down.
  - New Tables, B and BB, in operation at the 40" Mill, O.H.
- 1947
- Jan. -Received new Buff and Buff Transit.
  - Feb. -New shop built for Linde at the 19" Mill, Bessemer.
  - Mar. -#5 Blast Furnace completely rebuilt and blown in. Two bays added to cast house and one bay to granulated slag runway.
  - Apr. -New 48" Strip Mill in operation at O.H.
  - Bill Lantz quit to go with Bucheit.
  - Built turnaround track at west end of EWT.
  - Installed snubbers and new saw table at #1 CBW Mill.
  - Installed leveller at #3 EWT Mill.
  - Rhuele quit.
  - May -Completed 36" concrete pipe sewer from 48" Strip Mill to river.
  - Dave Lindsay let go after a fight with Strayer.
  - Rhodes, Reinerth and Moff quit.
  - June -#5 Straightener and Landis Facing Machines went into use at CBW Mill.
  - Rotoblast at #2 EWT Mill complete and in service.
  - July -Bruce Carpenter, OH Supt., quit.
  - Miller, from Chicago, new OH Supt.
  - #4 Blast Furnace relined to mantle.
  - Aug. -Leventry retired as G.M., John Graft the new G.M.
  - Landis Threading Machines in service at CBW Mill.
  - Laid 30" Water Line in river.
  - Sept. -Steve Wheeler left to go with UE&FCo in France.
  - Oct. -Linden quit at Galvanizing Shop.
  - Davies quit at OH.
  - Collins quit at Coke Works.
  - #5 Soaking Pit at OH rebuilt.
  - Reno gave up running instrument.

## 1947

- Dec. -Pusher at 10" Skelp Mill, Bessemer, reset and braced.
- Gas burner at #2 Blast Furnace installed.
- "O" Stand at 10" Skelp Mill, Bessemer, in operation.

## 1948

- Jan. 3 -Pasquale Gliemmo died at 6:20 am.
- 23 -Snowed 10" from 9 am to 9 pm.
- Jan. -Pipe Bundler at CBW Mill installed.
- #1 Landis Threader at #1 CBW Mill installed.
- Feb. -Enlarged uncoiler at #2 CBW Mill installed.
- #2 Abramson Straightener in jobbing floor relocated and in service.
- Anderson left at Coke Works.
- Mar. 19 -Bachtel let out at the Bessemer.
- Mar. -Meehan Boiler Works burnt down after being struck by lightning.
- Apr. 23 -Lawrence Parks died.
- Apr. -Rode scaffold down through #4 Blast Furnace. Patch job on lining.
- May -#1 Blast Furnace broke out at iron notch.
- June -Addition to coal crushing plant at Coke Works in operation.
- July -Kofler came to work in field party, Reno sat it out in the office.
- New machinery at #2 CBW Mill in operation.
- Raised track at old boiler house, Coke Works, removed.
- New concrete retaining wall at coal handling plant, Coke Works, installed
- Elevator at #3 Blast Furnace in service.
- Aug. 4 -Barney McCarthy quit.
- Aug. -New std. gauge track to 40" Mill scale pit at Bessemer in service.
- Bill Sims quit at CBW.
- McCoy made assistant to Hokelman.
- Burns fired at the 40" Mill, OH.
- Sept. -Beatty fired at the Scrap Yard.
- 22 $\frac{1}{2}$ "-19" Mill, Bessemer, electrified and in service.
- Bert Dye made MM at 40" Mill, OH.
- Stephens transferred from Blast Furnace to Corp. Sint. Plant Supt.
- Wells, Stephens' assistant, quit.
- Nov. -Parking lot at the Bessemer slagged.
- Dec. -New bell and hopper installed in #3 Blast Furnace.

## 1949

- Jan. 1 -Moved to the Lincoln Hotel.
- 15 -Moved to 129 West Glenaven Ave.
- Jan. -Fette retired at CBW and Roy Case took his place as Supt.
- Feb. 12 -Scott transferred from Supt. at Bessemer to metalurgical dept. at Cleve.
- Feb. -DeZutter came from Buffalo to take Scott's place.
- #3 Blast Furnace broke out at the iron notch. A week later broke out around the bustle pipe.
- Mar. 24 -Mumaw died at 2 pm.
- Mar. -George Campbell demoted from Asst. Stationery Eng. to working in gang.
- Apr. 16 -Snow.
- May -Sharpnack, MM at CBW Mill, sent back into machine shop.
- #4 Blast Furnace blew up badly.
- Hydrotester in #2 Shipping Bldg. in service.
- June 8 -Scattered frosts.
- 24 -George Warren laid off for good.
- Bill Steele quit.
- June -Murray, Asst. to G.M., quit.
- #5 Blast Furnace relined from mantle up. Salamander not taken out but much of the carbon block replaced. New bell and hopper installed.
- July -New saw at #1 CBW Mill in service.
- Aug. 5 -Reno retired. This was at company's request.

1949

- Aug. -#3 Hydropress at #3 EWT Mill in service.  
-New police booth at Bessemer in service.
- Sept. -Speer quit at the Bessemer.  
-#2 Hydropress at EWT Mill in service.  
-New fence put up at west end of Coke Works.
- Oct.1 -Strike started.
- Nov.4 -First snow.  
9 -Returned to work. Worked the first two weeks of strike, on vacation the next two, then loafed for seven working days. Got half a day's pay for the 31st of Oct. and a full pay for first half of Nov.
- Dec. -#6 Pit Furnace at OH rebuilt.  
-Turbo-Blower at Bessemer in service.  
-Bill Williams let out at the Bessemer, was stationery engineer.  
-Jimmy Garcia out at the Coke Works.  
-Paul Fry retired.  
-Dick Hagen forced out of lub. eng. job. Given job in machine shop.  
25 -Paul Meehan fired for not reporting to work on 24th.

1950

- Jan.1 -Dave Jenkins demoted to Chief Draftsman.  
12 -McLain started to work.  
30 -Bill Dobson let out of Labor Dept.
- Jan. -#4 Blast Furnace completely relined, carbon block in hearth and cast house rebuilt.
- Feb.22 -Roy Case fired. Hildebrand, his assistant, went back to Steel and Tubes  
Harry Jones became Supt., CBW, and McClintock his assistant.  
Conklin became assistant at EWT.
- Mar.17 -Electric drive on 40" Blooming Mill, Bessemer, in service.
- Apr.22 -Moved to Mrs. Funk's house.
- June 7 -Took delivery of Plymouth coupe.  
19 -Carl Cerull and Dave Ohl made Assistants to Stauffer.  
-McLain quit without notice.
- June -Glenn out as MM and Bill Carpanza in at CBW.  
-Diamond Steel scrapped old blowing engine at the Bessemer.
- July -Diamond Steel scrapped steam engine and generator at blast furnace power house.
- Aug. -Shutrum finished the four service buildings for blast furnace electrical, transportation, combustion engineers and riggers.  
-Heller-Murray finished welfare building at Coke Works.  
-New coke battery in service.
- Sept. -#2 CBW Furnace rebuilt with two new recuperators by Salem Eng.  
24 -Big smoke cloud from Canada came over and made it almost dark from 2 to 4:30 pm.
- Oct. -McCoy out as Assistant to Hoekleman and Kissavk in.  
-Diamond Steel tore down boiler house at 40" Mill, OH.
- Nov.11 -First snow.  
20 -Dan Hernon died.  
24 -The big snow. About two feet fell in 24 hours. Missed two days work.
- Nov. -Diamond Steel tore down east boiler house at Bessemer.
- Dec. -Dan Valentine promoted to boilermake foreman and Bill Montgomery, Asst  
21 -Femoral nerve in left leg started to hurt. Very bad on 23rd. Was able to go to work on 26th.

1951

- Jan.1 -John Dunleavy retired.  
2 -Siglow started with us.  
25 -Miller transferred to Alabama and Cahill brought back here as OH Supt.  
31 -Tony Dean left Eng. Dept .

1951

- Feb.7 -Nerve gave way on right side of face in am.  
 Apr.7 -Face nearly back to normal after two months.  
 15 -Welfare Bldg.at CBW Mill in use.  
 16 & 17-Snow flurries.  
 June -#1 Blast Furnace relined and high pressure top installed.  
 -McLaughlin made Supt.,T.& L.  
 July -New office at Coke Works in use.  
 8 -Scrap chopper at #2 EWT Mill in use.  
 Aug.2 -Bell and hopper replaced on #2 Blast Furnace.  
 13 -Conklin fired at EWT.  
 -Charley Leonard quit.  
 14 -X-Ray Gauge at 48" Strip Mill in service.  
 Sept. -New ore bridge at #1 Ore Yard in service.  
 8 -First frost.  
 -#3 Blast Furnace relined from mantle up,replaced bell and hopper,etc.  
 18-Strayer fired for drinking.  
 Oct. -New dipping tank and conveyor at north pot,Galv.Shop,in service.  
 -George Walker fired at EWT.  
 -Harry Jones in charge of both EWT and CBW Mills.  
 Nov.1 -Maughan made Supt.,EWT,under Jones.  
 -First snow.  
 Dec. -McClintock made Supt,CBW,and Weedon,Asst.Supt.

1952

- Jan.17 -Very severe rain and electrical storm in evening.  
 Feb.15 -T.R.Smith quit voluntarily as Safety Supervisor.  
 Mar. -Changed crank shaft on engine at 40" Mill,OH.  
 Apr.15 -Heavy snow started at 6 am,lasted until noon.  
 -Bottle cars in use to Bessemer.  
 30 -Steel strike.  
 May -Dick Hagen died.  
 31 -Dingledy fired for dickering for another job.  
 June 2 -Strike started on pm.  
 12-Muntz television installed.  
 30-Stopped by pickets at office,lasted one day.  
 July 27-~~Strike~~ strike over.  
 Aug. -We made a mistake of 8 feet in location of scrap hole for chopper at  
 #3 EWT.  
 -New columns and beams installed at coverter,Bessemer.  
 -Slabs put under south rail of gantry,Bessemer Converter.  
 Sept. -New splitter and chopper installed and leveller relocated,#3 EWT.  
 Oct. -Steam in 12" pipe line to Coke Works.  
 3 -First frost.  
 20 -First snow.  
 Nov. -Bundling rack at CBW in use.  
 -Shutrump completed retaining wall around office at Coke Works.  
 -Barney McCarthy died.  
 Dec. -McClintock made Supt.and Maughn his Asst. at EWT.  
 -Weedon made Supt.and Kline his Asst. at CBW.  
 -Johnson made Supt.and Beale his Asst at Converter,Bessemer.  
 17 -Ed Maurice operated on.

1953

- Jan.1 -Carl Cerull demoted from Asst.Chief Engineer.  
 5 -Ladle pit for direct hoist at OH in use.  
 Feb.4 -Ed Maurice's leg amputated above knee.  
 13 -United E & C closed their office and all personnel left.Boiler house  
 and precipitators complete.

1953

- Apr. 17 & 18 - Snowed all night and following day.
- 23 - Siglow laid off.
- May 22 - 3 $\frac{1}{2}$  inches of rain fell.
- 31 - Feisley and Reese transferred to Industrial Eng. Dept.
- Kofler transferred to Labor Dept.
- July - Buehler and Sedlock came to field engineers on #5 Blast Furn. job.
- #5 Blast Furnace relined from mantle up, bell and hopper replaced.
- 10 - Strang and Morrow quit the Masonry Dept.
- 30 - Dave Wagar fired after an argument with Jenkins.
- Aug. 1 - Dutch Wayland fired at 48" Strip Mill.
- Went to Corning and saw Joe Lombardo after 31 years.
- Sept. - #7 and 8 Pit Furnaces completely rebuilt with new covers for cover cranes.
- Oct. 3 - Crank shaft on engine at 40" Mill, OH, changed.
- 30 - First frost.
- Went to Kenton and Wapakoneta on vacation. Kenton seemed much changed, Wapakoneta much the same.
- Nov. - Shutrump finished south property line wall at Coke Works.
- 4 - First snow flurry.
- 14 - #4 Blast Furnace shut down.
- 18 - Cahill out at OH. Kappenhagen the new OH Supt.
- Dec. - Extension to Stop 5 Parking Lot in use.
- 5 - #5 Blast Furnace banked.
- 6 - Went on four days a week.
- 7 - Harmon returned as Elect. Supt. Pebbles demoted to Asst.
- 8 - Johnson out as Masonry Supt. Stern is new Supt.
- 14 - Went on three days a week.
- 19 - #2 Blast Furnace banked.

1954

- Jan. 6 - Koppers started on benzol plant.
- 10 - Ed Ware retired.
- 13 - Stern, Masonry Supt., quit.
- 18 - Ruth took Stern's place.
- Mar. 15 - Kofler laid off at Labor Dept.
- 18 - Feisley laid off.
- 19 - Sobers and Reese laid off.
- 24 - Sedlock quit.
- May - Raked out #5 Blast Furnace.
- June - Patched brick in #5 Blast Furnace.
- Aug. 13 - McCormack died.
- Sept. 10 - McCoy out as MM, EWT.
- 15 - Sholtis quit.
- 22 - Wrobleski laid off.
- 27 - Wall and Dickson went on four days a week.
- Oct. 13 - Tindle retired.
- 15 - 4.31 inches of rain.
- 27 - Reyner quit.
- 31 - First snow.
- Nov. 15 - Hall quit.
- Dec. 16 - Wall went on five days a week.
- 27 - Reese returned.

1955

- Jan. 1 - Dickson went on five days a week.
- 10 - Beatty retired.
- 14 - Adele quit, baby.
- 17 - #5 Blast Furnace blown in.
- 25 - Betty called back.

1955

- Feb.15 -Irene Furlong started in office.  
 26 -#2 Blast Furnace lit after relining from mantle up.High pressure top,new bell and hopper installed.
- Mar. -Vic Hamilla went blind.  
 -Charlie Yetter brought back to office.  
 23 -Jack Allen started with field engineers.  
 28 -Feisley returned.  
 30 -Reese went to main office.
- June 6 -Coleman started for summer.  
 17-Ruth,Masonry Supt.,left.  
 20-Anderson,from Warren,took his place.
- July 1 -CIO struck at 12:01 am.Strike stilled before noon.  
 5 -Drove sheet piling and poured concrete under north ore yard wall at sinter plant.  
 9 -Installed new bell and hopper at #1 Blast Furnace.
- Aug.1 &-2-Made building repairs at Converter,Bessemer.  
 19 -Tommy Howard forced to retire.
- Sept.1 -Crawford started.  
 13-Coleman returned to school.
- Oct.1 -Dave Ohl went to Warren.  
 17 -Hough became Asst.Chief Eng.
- Nov.4 -First snow.  
 28 -Eggleston transferred to Cleveland,Armbrust became Coke Works Supt.
- Dec. -Expander foundations finished.  
 31 -Hokelman resigned to go to Chicago for Sheet & Tube.  
 20 -Dave Pebbles retired.

1956

- Jan.1 -Kukilinski succeeded Hoekelman as Mechanical Supt.  
 13 -#3 O.H.Furnace lit after being completely rebuilt.Idle over two years.
- Feb.25 -TV antenna blew over in a very strong wind storm.  
 27 -Frank Miller started to work as expediter.
- Mar.6 -John Ferguson died.  
 16 -About 10" of snow.  
 23 -Chris Dalambakis returned to the Labor Dept.  
 29 -##4 Blast Furnace lit.
- Apr.1 -Milligan took over as Electrical Engineer.  
 17 -Lost two concrete forms at the flues of #11 O.H.
- June 1 -#4 Blast Furnace shut sown and raked out.  
 2 -Ensley Reno died of a stroke.  
 23-18" Cast Iron Pipe installed under hot metal track at B&O underpass.  
 -Big storm did much road damage at Struthers and Campbell.
- July 1 -Strike started at 12:01 a.m.
- Aug.4 -Strike over,returned to mill.Worked or took vacation during strike.  
 -North end of coal bridge blown off track about 5:30 p.m. North end was out of line 45'-6".
- Sept.12-Put pressure on first pipe in the expander on a tryout.  
 25-Gyromat at #1 C.B.W. in operation.  
 28-Diamond Steel finished repairs on skull cracker structure.
- Oct.8 -Yakubec came down from Eng.Dept. to replace Miller.  
 15 -DeZutter became Supt.of 48" Strip Mill.  
 -Schettler became Supt.of the Bessemer Plant.  
 -Ransom became Supt.of the Roll Turners.  
 27 -Harold Warnock died.  
 31 -Frank Miller quit to got with Mesta at New Castle.  
 -Perman quit at the Eng.Dept.
- Nov.3 -New crane at Skull Cracker in operation.  
 -The first snow;light.

## 1956

Dec.10 -Plastic coating equipment went into service at Bessemer.

## 1957

Jan.16 -Gyromat at #2 E.W.T.in operation.  
 18 -Bessemer Converter gantry crane repaired by Diamond Steel. Track taken up and reset in concrete.  
 28 -Raymond Gray started with Field Engineers.  
 Feb.5 -Conc.floor poured in three east bays of Galv.Bldg.  
 11 -East circular track at 40" Merry-Go-Round renewed.  
 28 -Installed new bed plates under drives at "1 E.W.T.  
 Mar.1 -Kappenhagen became Supt.of all steel making operations in district.  
 8 -Welfare building behind Bessemer soaking pits burnt.Rebuilt at once.  
 Apr.4 -#4 Blast Furnace blown down.  
 -New fence put in along dump on Powers Way.  
 27 -Irving Johnson,former Masonry Supt.,died.  
 May 3 -Concrete road put in between C.B.W. and Galv.Shop.  
 7 -Cincinnati Milling Mach.Grinder installed at O.H.Roll Shop.  
 15 -Finished retaining wall and foundation for add.to C.B.W.Shipping Bay.  
 June 15-Kline became Asst.Supt.at 48" Strip Mill.  
 -Erdis became Asst.Supt.at C.B.W.  
 24-#2 Blast Furnace broke out at iron notch.  
 July 5 -#2 Blast Furnace back in operation.  
 Aug.7 -O.H. 40" crankshaft changed.  
 Sept.20-Vic Chartener died of lung cancer.  
 27-First frost,fairly heavy.  
 Oct.25 -Russel Jones let out as Asst.Supt.at Bessemer. Waggener new Asst.  
 26 -A little snow in the air.  
 29 -Pollack pulled out after a rebuild on #3 Blast Furnace.Furnace not finished,company to finish.Salamander drained,carbon block replaced completely relined,new bell and hopper,etc.  
 Nov.11 -Feisley laid off  
 Dec.1 -Went on 4 days a week.  
 8 -All open hearths idle,5 were operating.#1 Bl.Fce.only operating.  
 26 -Samuel J.Liggett died at 9 a.m.  
 29 -Five open hearths went back into operation.  
 31 -New recuperators installed at #1 C.B.W. Furnace.

## 1958

Jan.8 -New cleaning facilities at Pipe Coating Shop completed.  
 31 -Longstreet,Horgan,Evans and Harmony forced to retire.  
 Feb.1 -Went on three days a week.  
 -Ed.Rogers made General Foreman of Boiler Shop.Valentine became a foreman.  
 10 -Double-spindle facing machine,gyromat and straightener in Job Shop and Threading Bay at C.B.W. in operation.  
 Mar.31 -Bruce Wall died of a heart attack in the office about 1 p.m.  
 June 7 -Frost this morning.  
 16-Went on four days a week.  
 30-Went on five days a week for a while.  
 -County rebuilt the four Center St.bridge piers at O.H.Roll Shop.  
 July 7 -Feisley returned to work.  
 9 -Dave Ohl returned to Youngstown.  
 -Hough took over Stouffer's duties,but Stouffer remains on the payroll  
 Dave Ohl is the assistant.  
 15-Koppers finished the rebuild of the Sintering Plant.  
 Aug.3 -The relocation of the #3 Electric Weld Mill completed.  
 4 -Went on four days a week.

1958

- Aug.5 -#5 & 6 B. & O. cutoff machines installed at #3 E.W.T.
- 6 -Bundling machine on #2 Finishing Floor at #2 B. & C. Tube completed.
- Sept.8 -New Pangborn Cleaner at #3 E.W.T. completed.
- Oct.2 -Heavy frost.
- 5 -Installed new 40" Mill Housing and new base under the Crop Shear at the O.H. 40" Mill.
- 6 -Cook returned to work after being sick since Aug.28.
- 18 -#3 Blast Furnace lit.
- Nov.5 -Took off #1 Blast Furnace.
- 14 -Bill Carpanza quit as M.M. at the B. & C. Tube.
- 21 -Snow in the evening.
- Dec.27 -New dust collecting system for both pots in operation at Galv. Dept.

1959

- Feb.2 -Farrow Tester installed at #3 E.W.T.
- 9 -West on five days a week.
- Mar.1 -#5 Blast Furnace blown in.
- 20 -Kappenhagen transferred to the Chicago District.
- May 8 -Mabel Dickson died.
- 16 -Heavy frost.
- June 1 -Joe Pavlik promoted to Rigger Foreman.
- 15 -Allen, Gray and Feisley went on salary. Practically the whole eng. dept.
- 18 -Reset the bearing stands under three bearings just east of the engine at the 16-14 Mill, O.H.
- July 15 -Steel strike started.
- 18 -Left on vacation to New York City on the Erie in the evening.
- 25 -Got home from New York about noon.
- Sept.17 -Heavy frost this morning.
- Nov.2 -First snow squalls.
- 7 -Supreme Court upheld the Taft-Hartley Act. Men started to return to work on the 11 pm shift.
- 22 -Fire at dust collector bin, Galvanizing Dept.
- Dec.11 -Ground caved in along north side of 7' )" city sewer opposite the scale pit at the 22 $\frac{1}{2}$ -19 Mill at the Bessemer about 1:45 pm.
- 31 -W.I. Manley retired as Asst. Gen. Manager.
- Vic Drebes retired as Line Gang Foreman.

1960

- Jan.4 -Steel strike settled.
- 8 -Pete Wilson retired as Supt. of Blast Furnaces. C.A. Anderson became Supt.
- 20 -Don Sobers came back to work with Field Engineers.
- 31 -John Stouffer retired as Chief Engineer.
- Feb.1 -J.A. Gerberry became Line Gang Foreman.
- 16 -Fernley Reed died this morning.
- 22 -Walter Cook operated on.
- 29 -Ultrasonic Tester after Jumbo Tester at #3 EWT completed.
- Mar.23 -Dave Pennock started with Field Engineers.
- Apr.5 -Crane Runway at 18" Hot Bed, OH, levelled, lined and grouted in.
- Baffle installed at #5 Blast Furnace Slag Pit.
- 12 -Kate Roberts died.
- 18 -Shipping Crane Runway at 10" Skelp Mill, Bess., lined and grouted. Girders repaired and new walkway installed.
- 24 -10" Bar Mill Furnace, Bess., rebuilt.
- June 1 -4 $\frac{1}{2}$ " to 8 5/8" Plastic Coating Mill construction job done.
- 12 -Plastic Coating Mill making acceptable coated pipe.
- 20 -Went on four days a week.



1960

- June 30-#1 Blast Furnace relined from mantle up, patched below mantle.  
#5 Trestle repaired.  
Sept. 16-Ted Kissack retired.  
Oct. 1 -First frost.  
24 -First snow.  
Nov. 30 -General retirement of all foremen and salaried employees over 65 years old and the retirement or firing of a large number under 65. Eng. Dept. lost Seifert, Waite, Yetter, Andrews and Jones.

1961

- Jan. 16 -Leon Lipson became Asst. Supt., Mechanical Dept.  
31 -Koppers practically completed Battery "C" at Coke Plant.  
-Plug conveyor in operation at #2 Plastic Coating Line.  
Mar. 1 -#1 and #2 Heating Furnaces at 16-14 Mill rebuilt from floor beams up. New flue built and lined with castible.  
6 -#3 Plastic Line coating pipe.  
12 -Pumps went into operation at the 21 $\frac{1}{2}$ -19 Mill Scale Pit at Bess.  
19 -Pumps went into operation at the 40" Mill Scale Pit at Bess.  
22 -Diamond Steel replaced six rings on #1 Soaking Pit Stack at Bess.  
Apr. 22 -Replaced bearing slabs and levelled cover crane rails on Pits 1, 2, 3 & 4 at Bessemer.  
-Reset mill shoe for #3 & #4 Passes at 19" Mill, Bessemer.  
-Reset Table AA at 40" Mill, Bessemer.  
-Replaced roof truss north of the Bessemer converters.  
May 30 -Heavy frost this morning.  
July 5 -#1 Blast Furnace lit this morning.  
-Gilford Davis, the carpenter foreman, died of a heart attack.  
6 -Ed. Weedon made Gen. Supt. of the Youngstown District.  
-John Erdis made Supt. of the C.B.W. Mills.  
18-Thermatool Welder at #2 E.W.T. in operation.  
31-Len Hough left this District to become Chief Engineer at Canton.  
Aug. 1 -Richard T. Richmond became Chief Engineer in place of Hough.  
Sept. 22-Shutrum finished putting a floor in the Gibson Run Culvert from Poland Ave. to about 75' south of the river.  
29-East End Bridge repairs done. Steel by Diamond Steel, concrete by Intrusion Prepackt.  
Oct. 1 -Ladle Lining Pit at east end of O.H. rebuilt.  
30 -Finished the repair work on #2, 3 & 4 Ore Trestle. Very extensive repairs included raising columns, new column stubs, new cross-girders and stringers.  
Nov. 8 -First snow, no frost.  
11 -First frost that I noticed.  
30 -Al Olson and Knute Harmon left. Will retire on Dec. 31.  
Dec. 19 -Straightener for rounds at 16-14 Mill, O.H., completed.  
23 -#2 C.B.W furnace overhauled and flue repaired.  
29 -Howard Smith and Horace Buckles retired.  
31 -John Graft retired as General Manger. Ross Philips became the new General Manager.  
-C.W. DeZutter retired as Supt. of the 44" Strip Mill. E.L. Kline became the new Supt.

1962

- Jan. 14 -Erected new soaking pit crane at 40" O.H. Pits.  
17 -Walter Cook started to work out of the Market St. Office.  
-Don Rearick became Electrical Supt.  
-Dory became Line Gang Foreman.  
Feb. 15 -Installed new pickling tanks on north side of Galvanizing Dept.  
Mar. 3 -Lengthened slab transfer ay 40" Mill, O.H.  
27 -Coke Works Battery "C" in operation.

1962

- Apr.14 -#2 Blast Furnace rebuilt. Two new columns,new shell,strengthened shell,ceramic brick bottom with carbon brick lining to mantle, 21,23 & 24 stoves renovated.
- 24 -Walter Cook died at the North Side Hospital about 4:30 p.m. Autopsy showed that a weak spot in the aorta broke.
- May 3 -Six bins under the trestle at #1 Blast Furnace fell in in the early morning. No one hurt.
- June 4.-Mrs.Funk had a stroke in the night.
- July 19-Louis Yakubek left the company today.
- Aug.1 -Paul Crawford officially became Field Engineer.
- Oct.1 -Walter Cook,Jr.,became General Foreman,Inspection,E.W.T..
- 22 -Angle straightener at Bessemer in operation.
- 24 -First snow in afternoon,first frost and freeze at night.
- 29 -Harry Anderson became Supt.of Construction for No.5 E.W.T..
- Nov.8 -Knocked the Berger transit over. \$202 repair job.
- 15 -Angle straightener at 16-14 Mill,O.H. in operation.
- Dec.12 -John DiMenno retired as General Electrical Foreman,Blast Furnaces.

1963

- Jan.1 -E.L.Weden became Asst.Gen.Manager.
- Skinny Williams retires as Elect.Foreman at the B.& C.Tube.
- 21 -Work started on #5 E.W.T. at temporary wooden stores building and at west end of #3 E.W.T.
- 24 -Eleven below zero this morning.
- Feb.20 -Poured first concrete in #1 Ship.Bldg.on #5 E.W.T.
- Mar.4 -Fred Hohlock went to work with Field Engineers.
- Apr.3 -Mrs.Funk had an insulin shock;to hospital.
- 7 -Eva Liggett died about noon of a heart attack.
- 10 -Eva buried.
- 19 -Mrs.Funk came home.
- May 1 -About two inches of snow this morning.Cool all day.
- As of today: Gene Klein,Supt.of Electric Weld Mills; Kenny Wagoner, Supt.of #0",21 $\frac{1}{2}$ "-19",L6-14" & 44" Mills,O.H.; Lew Shettler,Supt., Bessemer Plant and Johnson,Asst.to Shettler.
- 24 -Heavy freeze this morning.
- June 24-Went on 3:30 to 12 mid.shift on #5 E.W.T.
- Aug.25 -Returned to the day shift.
- Oct.22 -Turned #5 E.W.T.Mill over for the first time.
- 30--First piece of pipe welded in #5 Welder,6 5/8" O.D.
- Nov.2 -First snow early in the morning.
- 13 -Shutrump finished on #5 E.W.T.
- 27 -Rolled last piece of pipe on #3 E.W.T.Mill about 1:00 a.m. Strip Mill and #2 E.W.T. are also done.Will not work again.
- Dec.16 -Charlet Baer became Asst.Supt.of the E.W.T. Foley became Finishing Floor Foreman. Kaden is at the Plastic Coating Mill.

1964

- Jan.4 -Started to move #5 E.W.T. storeroom to the B.& C.
- 10 -Feisley laid off effective this date.
- 12 & 13-Had 15" of snow.
- 17 -Big layoff of supervisory employees.
- Mar.18 -Marie Funk went to Gertrude's place witha light heart condition.
- 20 -Took Marie Funk to the hospital at 1:30 am with insulin shock.
- Apr.14 -Moved into the Colonial Motel in Boardman.
- June 7 -Marie Funk died at 8 am.
- Aug.28 -Ceased ringing time cards.
- 31 -Feisley returned to work.
- Sept.13-Jim Kenny died.
- 14-First frost.
- 15-Schuman retired.

1964

- Sept.16- Bill McDowell died.  
27- Helen Naughton died.  
Nov.20 - Snow in the night.  
Dec.4 - Jack Allen was transferred to Market St. to take Conti's place.

1965

- Feb.12 - Harry Anderson, Supt. of Construction, finished up this date.  
Went to Cleveland as Masonry Supt.  
15 - Ed Rogers became Acting Supt. of Construction.  
July 31- Walter Shields quit to take a job in Tampa, Fla.  
Aug.7 - Went to Duquesne.  
Sept.9 - Lou Kukukinski became Supt. of Construction.  
Oct.6 - First frost and freeze.  
24 - First snow flurries.  
Dec.31 - Retired at end of day on this date.

1966

- Jan.22 & 23- Started to snow in the early afternoon of the 22nd. Apparently kept it up for most of the night. Measured  $11\frac{1}{2}$  inches about 9:30 on the morning of the 23rd.  
Jan.28- Thermometer at -9 at 7 a.m.  
Feb. - Winter low -8.  
Apr.22 - George Strayer died.  
May 9 - Started to snow some time after midnight and continued to 10 a.m. Temperature 31 at 9:30 a.m.  
May 10 - Temperature in the early morning was 21.  
June 4 - T.A. Roberts died.  
Oct.21 - First ~~snow~~ <sup>frost</sup> here that I saw.  
Oct. - The 'Anna' Blast Furnace at Struthers completely torn down and the site cleared off.  
Nov.3 - First snow here.

1967

- Feb.8 - The winter low at -8.  
Mar.7 - George Schraum was killed at the 2nd Street crossing by a P & LE freight when he walked in front of the engine.  
19 - The temperature was 4.  
Apr.24 - Started to snow between 12 and 1 a.m. Probably  $\frac{1}{2}$  to 1 inch total and it stopped by daylight.  
May 6 - Snow and rain falling at 8 a.m. Snow stopped about 9 a.m.  
Sept.25-- Temperature was 33 and we had our first frost.  
Oct.25 - A small amount of snow.  
Oct.29 - Temperature was 20 and we had a very heavy frost.

1968

- Mar.15- Republic Steel announced that the Warren and Youngstown Districts had been consolidated as the Mahoning Valley District. Philipps went to Gadsden and Weedon remained as Asst. Dist. Manager, subject to the District Manager who had Warren.  
Apr. 1 - Richmond returned to Cleveland to the General Office.  
Sept.18- Earl Smith died at 81.  
Sept.26- Michael F. Marrie died at 10 a.m. He was 59 years old.  
Oct.29 - First snow and sleet and so far it never frosted here.  
Dec.23 - Harold Ellsworth died at 6:30 p.m. at the Lakeside Hospital.  
Dec.26 - Harold Ellsworth buried at Lowellville Cemetery.

1969

- Mar.17 -Aunt Lily took sick,did not seem serious at first.  
22 -Dr.Camp sent medicine to her by Mary Davies.  
24 -Dr.Camp called.  
Apr.1 -Dr.Camp called.  
6 -Took Aunt Lily to the South Side Hospital about 5:30 p.m. Ruth had been home and left.  
11 -Aunt Lily died at about 1:30 a.m.  
12 -Aunt Lily buried.  
May 9 -Francis C.Batteiger died of a heart ailment at 5:05 p.m. at the Sleigh Bell Nursing Home.

1970

- Feb.13 -Roy C.Goodhue died of a heart attack in Chicago.  
Feb.13 -Horace C.Buckles died of a heart attack at South Side Hospital.  
Feb.21 -Arthur N.Struble died of a heart attack at his home.Gertrude was with him at the time.  
May 16 -Mrs.Bruce Wall died at 1:30 p.m. at Jensen Beach,Florida.  
Interment at Poland on May 19.  
June 18-John Koletich died at Cafaro Hospital at about 4:00 P.M.  
Jack Stiles was with him at the time.  
July 22-George James died at 3:20 a.m. at his home. He had been sick for nine months with Parkinson's Disease and arteriosclerosis.  
Aug.13 -Moved into Gertrude Struble's apartment.

1971

- Feb.19-Bill Maurice had a bad heart attack about midnighon this date. Was placed in the intensive care ward and stayed there almost a month.  
Apr.25-Bill Maurice came home from the hospital.  
June 21-Grace Kearns died at the age of 99.  
Dec.17-Hoyte Sexton died in Lisbon at the age of 66.

1972

- July 18-Gavril Moldovan died of a heart attack at 6:00 a.m. at Paul's house. He had been operated on for cancer sometime before.  
Oct.10-25 degrees and a freeze.  
Oct.27-Bill Maurice died about 10 a.m. after another heart attack about 8:00 a.m.  
Dec.23-Charley Leonard told me that Scotty Martin of the Line Gang died recently.  
Dec.27-Louie Gliemmo died of cancer about 5:45 p.m.

1973

- Jan.18-Vic Drebis of the line gang died of emphysema.

1974

- Apr.11-Jack Stiles had a stroke affecting his right side, but could walk and look after himself. Was in hospital for a week.  
Aug.9-Met Frank.Tusinac,330 Johnston Place, who works on the stretch mill finishing floor.

1975

- Feb.1-Bill Sonnenlitter die of a heart attack at 3:15 p.m. at hosp.  
Apr.13-Jim Irvin died of post operstive complications.  
Apr.29-Gerald Feisley died at University Hospital,Cleveland after a one month illness. Died of a bleeding stomach ulcer.  
May 16-Saw Mickey Petro of Pollacks this evening. Is Field Supt. for Pollack. (Francie Walsh's old job.)

1975

- June 14-Slipped in bathroom and hit water tank on commode. Loosened two front teeth, cut inner upper lip, etc.
- June 26-Saw Tom Perry at the Mall. Was in the Accounting Dept. and is retired. In bad shape physically but very good spirits.
- Aug. 4-Elmer Liggett died in his sleep from a cerebral hemorrhage. Ruth found him in the morning.
- Sept. 7-Harold Olsen (Al's brother) of the Pipe Shop died of a heart attack.
- Sept. 19-William H. (Buzz) Johnson died of a heart attack at 0215 at North Side Hospital.
- Sept. 30-Dr. Mangie pulled five upper teeth and put in upper plate furnished by Dr. Preston.